

Date	Time	instrument	analyte	reading	detection_flag	detection_limit	units	location_code	latitude	longitude	location_description	comments	additional_comments
04/06/2013	21:07	MultiRAE	H2S	<		1 ppm	8A		34.96320694	-92.42611794	South side of 8 Starlite Rd	Exhaust fumes odor; Crude oil odor; Visible Oil; boom present; Area evacuated; Residence; Workers not present; Slight Odor;	decon startion set up near boom visible by ditch ATRID1852 boom in ditch
04/06/2013	21:08	MultiRAE	VOC	<		0.1 ppm	8A		34.96320694	-92.42611794	South side of 8 Starlite Rd	Exhaust fumes odor; Crude oil odor; Visible Oil; boom present; Area evacuated; Residence; Workers not present; Moderate Odor;	decon stain set up visible product in ditch ATRID1852 crude oil odor boom around ditch
04/06/2013	21:11	UltraRAE	Benzene	<		0.05 ppm	8A		34.96320694	-92.42611794	South side of 8 Starlite Rd	Crude oil odor; Visible Oil; boom present; Area evacuated; Residence; Workers not present; Moderate Odor;	visible oil in ditch ATRID1852 light generator near no visible oil ATRID1852
04/06/2013	21:14	MultiRAE	VOC	<		0.1 ppm	8B		34.96316738	-92.42625046	South side of 8 Starlite Rd	Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	ATRID1852
04/06/2013	21:15	MultiRAE	H2S	<		1 ppm	8B		34.96316738	-92.42625046	South side of 8 Starlite Rd	No Visible Oil; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	ATRID1852
04/06/2013	21:15	UltraRAE	Benzene	<		0.05 ppm	8B		34.96316738	-92.42625046	South side of 8 Starlite Rd	No Visible Oil; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	batch 211074 ATRID1852
04/06/2013	21:20	MultiRAE	VOC	<		0.1 ppm	12A		34.96338292	-92.42648566	East side of 12 Starlite Rd	No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	decon station set up on street ATRID1852
04/06/2013	21:21	MultiRAE	H2S	<		1 ppm	12A		34.96338292	-92.42648566	East side of 12 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	decon station set up on street ATRID1852
04/06/2013	21:22	UltraRAE	Benzene	<		0.05 ppm	12A		34.96338292	-92.42648566	East side of 12 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	decon station set up on street batch 211074 ATRID1852
04/06/2013	21:23	MultiRAE	VOC	<		0.1 ppm	12B		34.96349768	-92.42647133	East side of 12 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1852
04/06/2013	21:24	MultiRAE	H2S	<		1 ppm	12B		34.96349768	-92.42647133	East side of 12 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1852
04/06/2013	21:24	UltraRAE	Benzene	<		0.05 ppm	12B		34.96349768	-92.42647133	East side of 12 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	batch 211074 ATRID1852
04/06/2013	21:27	MultiRAE	VOC	<		0.1 ppm	16A		34.96338471	-92.42675423	East side of 16 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	Dumpster located on street ATRID1852
04/06/2013	21:29	MultiRAE	H2S	<		1 ppm	16A		34.96338471	-92.42675423	East side of 16 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	Dumpster located on street ATRID1852 batch 211074
04/06/2013	21:29	UltraRAE	Benzene	<		0.05 ppm	16A		34.96338471	-92.42675423	East side of 16 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	Dumpster located on street ATRID1852
04/06/2013	21:32	UltraRAE	Benzene	<		0.05 ppm	16B		34.9635051	-92.42674934	East side of 16 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	batch 211074 ATRID1852
04/06/2013	21:31	MultiRAE	VOC	<		0.1 ppm	16B		34.9635051	-92.42674934	East side of 16 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1852
04/06/2013	21:31	MultiRAE	H2S	<		1 ppm	16B		34.9635051	-92.42674934	East side of 16 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present; No odor; Vac Trucks Present; boom present; Area evacuated; Residence; No work activity; Workers not present;	ATRID1852 Vac truck present but not being used Boom in ditch on the street ATRID1852 vactrack present not being used Boom in ditch on the street ATRID1852 batch 211074
04/06/2013	21:35	MultiRAE	VOC	<		0.1 ppm	20A		34.96337914	-92.42699801	East side of 20 Starlite Rd	No odor; No Visible Oil; Vac Trucks Present; boom present; Area evacuated; Residence; No work activity; Workers not present;	Vac truck on street but not being used Them located in drainage ditch on street ATRID1852
04/06/2013	21:38	MultiRAE	H2S	<		1 ppm	20A		34.96337914	-92.42699801	East side of 20 Starlite Rd	No odor; No Visible Oil; Vac Trucks Present; boom present; Area evacuated; Residence; No work activity; Workers not present;	ATRID1852
04/06/2013	21:39	UltraRAE	Benzene	<		0.05 ppm	20A		34.96337914	-92.42699801	East side of 20 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1852
04/06/2013	21:41	MultiRAE	VOC	<		0.1 ppm	20B		34.96350363	-92.42699492	East side of 20 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1852
04/06/2013	21:41	MultiRAE	H2S	<		1 ppm	20B		34.96350363	-92.42699492	East side of 20 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1852
04/06/2013	21:42	UltraRAE	Benzene	<		0.05 ppm	20B		34.96350363	-92.42699492	East side of 20 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present; No odor; No Visible Oil; Vac Trucks Present; Area evacuated; Residence; No work activity; Workers not present;	batch 211074 ATRID1852
04/06/2013	21:44	MultiRAE	VOC	<		0.1 ppm	24B		34.96338229	-92.42725689	East side of 24 Starlite Rd	No odor; No Visible Oil; Vac Trucks Present; Area evacuated; Residence; No work activity; Workers not present;	vac track present in street but not being used , small trench between houses ATRID1852 Vac truck on street not being used trench between house ATRID1852 batch 211074
04/06/2013	21:49	MultiRAE	H2S	<		1 ppm	24B		34.96338229	-92.42725689	East side of 24 Starlite Rd	No odor; No Visible Oil; Vac Trucks Present; Area evacuated; Residence; No work activity; Workers not present;	Back tracked located on street not being used Trench between houses ATRID1852 batch 211074
04/06/2013	21:50	UltraRAE	Benzene	<		0.05 ppm	24B		34.96338229	-92.42725689	East side of 24 Starlite Rd	No odor; No Visible Oil; Vac Trucks Present; Area evacuated; Residence; No work activity; Workers not present;	trench between homes ATRID1852
04/06/2013	21:53	UltraRAE	Benzene	<		0.05 ppm	24A		34.96348171	-92.42724502	East side of 24 Starlite Rd	No odor; No Visible Oil; Vac Trucks Present; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	trench between homes ATRID1852
04/06/2013	21:51	MultiRAE	VOC	<		0.1 ppm	24A		34.96348171	-92.42724502	East side of 24 Starlite Rd	No odor; No Visible Oil; Vac Trucks Present; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	trench between homes ATRID1852
04/06/2013	21:52	MultiRAE	H2S	<		1 ppm	24A		34.96348171	-92.42724502	East side of 24 Starlite Rd	No odor; No Visible Oil; Vac Trucks Present; Area evacuated; Residence; No work activity; Workers not present;	trench between homes ATRID1852 slight oil smell trench in yard
04/06/2013	21:54	MultiRAE	VOC	<		0.1 ppm	24C		34.96360648	-92.42720585	North side of 20 Starlite Rd	No Visible Oil; Visible Oil; boom present; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	Yard has been excavated ATRID1852
04/06/2013	21:54	MultiRAE	H2S	<		1 ppm	24C		34.96360648	-92.42720585	North side of 20 Starlite Rd	No Visible Oil; boom present; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	Yard has been excavated ATRID1852 batch 221074
04/06/2013	21:55	UltraRAE	Benzene	<		0.05 ppm	24C		34.96360648	-92.42720585	North side of 20 Starlite Rd	No Visible Oil; boom present; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	Yard has been excavated ATRID1852 Slight oil an exhaust odor
04/06/2013	22:05	MultiRAE	VOC	<		0.1 ppm	28B		34.96337909	-92.42750685	East side of 28 Starlite Rd	No Visible Oil; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	Light generator nearby ATRID1852 Slight oil an exhaust odor
04/06/2013	22:05	MultiRAE	VOC	<		0.1 ppm	28B		34.96337909	-92.42750685	East side of 28 Starlite Rd	No Visible Oil; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	Light generator nearby ATRID1852 bqтч 211074
04/06/2013	22:09	UltraRAE	Benzene	<		0.05 ppm	28B		34.96337909	-92.42750685	East side of 28 Starlite Rd	No Visible Oil; Exhaust fumes odor; Crude oil odor; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	l light generator slight oil and exhaust odor ATRID1852
04/06/2013	22:08	MultiRAE	H2S	<		1 ppm	28B		34.96337909	-92.42750685	East side of 28 Starlite Rd	No Visible Oil; Crude oil odor; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	light generator slight look and exhaust odor ATRID1852
04/06/2013	22:08	MultiRAE	H2S	<		1 ppm	28B		34.96337909	-92.42750685	East side of 28 Starlite Rd	No Visible Oil; Crude oil odor; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	light generator slight look and exhaust odor ATRID1852
04/06/2013	22:12	MultiRAE	VOC	<		0.1 ppm	28A		34.96351416	-92.42748061	East side of 28 Starlite Rd	Area evacuated; Residence; No work activity; Workers not present;	Area has been excavated ATRID1852
04/06/2013	22:12	MultiRAE	VOC	<		0.1 ppm	28A		34.96351416	-92.42748061	East side of 28 Starlite Rd	Area evacuated; Residence; No work activity; Workers not present;	Area has been excavated ATRID1852
04/06/2013	22:13	MultiRAE	H2S	<		1 ppm	28A		34.96351416	-92.42748061	East side of 28 Starlite Rd	No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	Area has been excavated ATRID1852

											batch 211074
04/06/2013	22:13	UltraRAE	Benzene	<	0.05 ppm	28A	34.96351416	-92.42748061	East side of 28 Starlite Rd	No Visible Oil; Visible Oil; boom present; No work activity; Workers not present; Crude oil odor; Visible Oil; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	Area has been excavated ATRID1852
04/06/2013	22:23	MultiRAE	H2S	<	1 ppm	32C	34.96349752	-92.42773831	East side of 32 Starlite Rd		slight oil odor ATRID1852
04/06/2013	22:24	UltraRAE	Benzene	<	0.05 ppm	32C	34.96349752	-92.42773831	East side of 32 Starlite Rd	Crude oil odor; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	slight oil odor batch 211074 ATRID1852
04/06/2013	22:22	MultiRAE	VOC	1.1	0.1 ppm	32C	34.96349752	-92.42773831	East side of 32 Starlite Rd	Crude oil odor; Visible Oil; No work activity; Workers not present; Slight Odor;	slight oil odor ATRID1852
04/06/2013	22:19	MultiRAE	H2S	<	1 ppm	32D	34.96340463	-92.42774521	East side of 32 Starlite Rd	Exhaust fumes odor; Vac Trucks Present; Crude oil odor; Visible Oil; Area evacuated; Residence; Workers present; Slight Odor;	2 van trucks present visible oil in yard
04/06/2013	22:21	UltraRAE	Benzene	<	0.05 ppm	32D	34.96340463	-92.42774521	East side of 32 Starlite Rd	Vac Trucks Present; Crude oil odor; Area evacuated; Residence; Workers present; Slight Odor;	slight oil odor ATRID1852
04/06/2013	22:16	MultiRAE	VOC	1.4	0.1 ppm	32D	34.96340463	-92.42774521	East side of 32 Starlite Rd	Exhaust fumes odor; Vac Trucks Present; Crude oil odor; Area evacuated; Residence; Workers present; Slight Odor;	batch 212074 slight oil odor
04/06/2013	22:30	MultiRAE	VOC	1.9	0.1 ppm	32B	34.96360344	-92.42773109	North side of 32 Starlite Rd	No Visible Oil; Crude oil odor; Area evacuated; Residence; No work activity; Workers not present; Moderate Odor;	2 vac trucks present ATRID1852
04/06/2013	22:32	MultiRAE	H2S	<	1 ppm	32B	34.96360344	-92.42773109	North side of 32 Starlite Rd	No Visible Oil; Crude oil odor; Visible Oil; Area evacuated; Residence; No work activity; Workers not present; Moderate Odor;	2 vac trucks present visible oil in yard
04/06/2013	22:32	UltraRAE	Benzene	<	0.05 ppm	32B	34.96360344	-92.42773109	North side of 32 Starlite Rd	No Visible Oil; Crude oil odor; Area evacuated; Residence; No work activity; Workers not present; Moderate Odor;	slight oil odor
04/06/2013	22:39	MultiRAE	VOC	0.7	0.1 ppm	32A	34.96357413	-92.42786323	North side of 32 Starlite Rd	No Visible Oil; Crude oil odor; Area evacuated; Residence; Community Center; Workers not present; Moderate Odor;	Equipment traffic on road ATRID1852
04/06/2013	22:40	MultiRAE	H2S	<	1 ppm	32A	34.96357413	-92.42786323	North side of 32 Starlite Rd	No Visible Oil; Crude oil odor; Area evacuated; Residence; No work activity; Workers not present; Moderate Odor;	Area has been excavated moderate oil odor
04/06/2013	22:41	UltraRAE	Benzene	<	0.05 ppm	32A	34.96357413	-92.42786323	North side of 32 Starlite Rd	No Visible Oil; Crude oil odor; Area evacuated; Residence; No work activity; Workers not present; Moderate Odor;	light generals near by ATRID1852
04/06/2013	22:46	MultiRAE	VOC	<	0.1 ppm	36D	34.96342707	-92.42798418	East side of 36 Starlite Rd	No Visible Oil; Vac Trucks Present; Area evacuated; Residence; No work activity; Workers present; Slight Odor;	Area has been escuvated light generator near by
04/06/2013	22:49	MultiRAE	H2S	<	1 ppm	36D	34.96342707	-92.42798418	East side of 36 Starlite Rd	No Visible Oil; Vac Trucks Present; Crude oil odor; Area evacuated; Residence; No work activity; Workers present; Strong Odor;	moderate oil odor ATRID1852
04/06/2013	22:50	UltraRAE	Benzene	<	0.05 ppm	36D	34.96342707	-92.42798418	East side of 36 Starlite Rd	No Visible Oil; Vac Trucks Present; Crude oil odor; Area evacuated; Residence; No work activity; Workers present; Slight Odor;	batch 211074
04/06/2013	22:52	MultiRAE	VOC	<	0.1 ppm	36C	34.96351985	-92.42796122	East side of 36 Starlite Rd	No Visible Oil; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	Area being activated
04/06/2013	22:53	MultiRAE	H2S	<	1 ppm	36C	34.96351985	-92.42796122	East side of 36 Starlite Rd	No Visible Oil; Crude oil odor; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	Bags of debris in area
04/06/2013	22:54	UltraRAE	Benzene	<	0.05 ppm	36C	34.96351985	-92.42796122	East side of 36 Starlite Rd	No Visible Oil; Crude oil odor; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	Moderate oil odor ATRID1852
04/06/2013	22:57	MultiRAE	VOC	0.7	0.1 ppm	36B	34.96366059	-92.42805142	North side of 36 Starlite Rd	Crude oil odor; Visible Oil; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	yard being excavated moderate oil odor ATRID1852
04/06/2013	23:03	UltraRAE	Benzene	<	0.05 ppm	36B	34.96366059	-92.42805142	North side of 36 Starlite Rd	Crude oil odor; Visible Oil; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	moderate oil odor
04/06/2013	23:04	MultiRAE	H2S	<	1 ppm	36B	34.96366059	-92.42805142	North side of 36 Starlite Rd	Crude oil odor; Visible Oil; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	hard being excavated moderate oil odor ATRID1852
04/06/2013	23:08	MultiRAE	H2S	<	1 ppm	36A	34.96360936	-92.42814123	North side of 36 Starlite Rd	No Visible Oil; Crude oil odor; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	moderate oil odor
04/06/2013	23:07	MultiRAE	VOC	0.2	0.1 ppm	36A	34.96360936	-92.42814123	North side of 36 Starlite Rd	No Visible Oil; Crude oil odor; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	yard being excavated
04/06/2013	23:09	UltraRAE	Benzene	<	0.05 ppm	36A	34.96360936	-92.42814123	North side of 36 Starlite Rd	No Visible Oil; Crude oil odor; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	yard being excavated bwtdch 211074 ATRID1852
04/06/2013	23:12	MultiRAE	H2S	<	1 ppm	40B	34.96350676	-92.42839371	North side of 40 Starlite Rd	No Visible Oil; Crude oil odor; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	2 vac tricks present, n no operating at the moment
04/06/2013	23:11	MultiRAE	VOC	0.3	0.1 ppm	40B	34.96350676	-92.42839371	North side of 40 Starlite Rd	No Visible Oil; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	slight oil odor
04/06/2013	23:13	UltraRAE	Benzene	<	0.05 ppm	40B	34.96350676	-92.42839371	North side of 40 Starlite Rd	No Visible Oil; Crude oil odor; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	slight oil odor traffic on street with equipment ATRID1852
04/06/2013	23:14	MultiRAE	VOC	0.4	0.1 ppm	40C	34.96349716	-92.4282334	East side of 40 Starlite Rd	No Visible Oil; Crude oil odor; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	2 vac trucks present but not operating at the moment
04/06/2013	23:15	MultiRAE	H2S	<	1 ppm	40C	34.96349716	-92.4282334	East side of 40 Starlite Rd	No Visible Oil; Crude oil odor; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	traffic of street with equipment
04/06/2013	23:19	UltraRAE	Benzene	<	0.05 ppm	40C	34.96349716	-92.4282334	East side of 40 Starlite Rd	No Visible Oil; Crude oil odor; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	slight odor ATRID1852
04/06/2013	23:21	MultiRAE	VOC	<	0.1 ppm	40D	34.96342675	-92.42823138	East side of 40 Starlite Rd	No Visible Oil; Exhaust fumes odor; Crude oil odor; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	slight oil odor
04/06/2013	23:22	MultiRAE	H2S	<	1 ppm	40D	34.96342675	-92.42823138	East side of 40 Starlite Rd	No Visible Oil; Exhaust fumes odor; Crude oil odor; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	traffic on street with equipment
04/06/2013	23:23	UltraRAE	Benzene	<	0.05 ppm	40D	34.96342675	-92.42823138	East side of 40 Starlite Rd	No Visible Oil; Exhaust fumes odor; Crude oil odor; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	moderate oil odor ATRID1852

04/06/2013	23:26	MultiRAE	H2S	<	1 ppm	40A	34.96350657	-92.42849401	North side of 40 Starlite Rd	No Visible Oil; Crude oil odor; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	slight oil odor ATRID1852 workers escuvating yard down street 2 light plans 2 dumpsters
04/06/2013	23:33	Gastec 121L	Benzene	<	0.05 ppm	40A	34.96350657	-92.42849401	North side of 40 Starlite Rd	No Visible Oil; Crude oil odor; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	wc no 20955 no discoloration ATRID1852 slight oil odor workers escuvating 6ard down street 2 light trees vac truck 2 dumpsters ATRID1852 workers escuvating yard at 50 shafetree 2 light plants vac truck down the street 2 dumpsters
04/06/2013	23:25	MultiRAE	VOC	2.4	0.1 ppm	40A	34.96350657	-92.42849401	North side of 40 Starlite Rd	No Visible Oil; Crude oil odor; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	batch 211074 confirmed by running test twice with me tubes ATRID1852 vac truck in drive way workers escuvating yard 2 dumpters 2 light plants ATRID1852 vac truck in drive way workers escuvating yard 2 dumpters 2 light plants ATRID1852
04/06/2013	23:27	UltraRAE	Benzene	0.05	0.05 ppm	40A	34.96350657	-92.42849401	North side of 40 Starlite Rd	No Visible Oil; Crude oil odor; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	workers escuvatijg yard ATRID1852 slight oil odor workers escuvating yard batch 211074 ATRID1852 workers in lunch but where escuvating yard vac truck in drive way moderate oil odor ATRID1852
04/06/2013	23:42	MultiRAE	VOC	<	0.1 ppm	44A	34.96376315	-92.4285727	West side of 44 Starlite Rd	Exhaust fumes odor; Vac Trucks Present; Crude oil odor; Visible Oil; Area evacuated; Residence; No work activity; Workers not present; Moderate Odor;	moderate oil odor ATRID1852 batch 211074 confirmed with second tube workers in lunch break but were just escuvating yard moderate oil odor ATRID1852 qc no 20955 no discoloration 500ml
04/06/2013	23:42	MultiRAE	VOC	<	0.1 ppm	44A	34.96376315	-92.4285727	West side of 44 Starlite Rd	Exhaust fumes odor; Vac Trucks Present; Crude oil odor; Visible Oil; Area evacuated; Residence; No work activity; Workers not present; Moderate Odor;	works just escuvating yard ATRID1852 moderate oil odor vac truck in drive way boom around release site as has been escuvated ATRID1852
04/06/2013	23:45	MultiRAE	H2S	<	1 ppm	44A	34.96376315	-92.4285727	West side of 44 Starlite Rd	Workers present; Slight Odor;	ATRID1852 vac trunk in drive way oil odor eorkers st lunch boom around release site ATRID1852 moderate oil odor boom around release site ATRID1852 moderate oil odor vac truck in driveway boom around release site workers in lunch
04/06/2013	23:45	MultiRAE	H2S	<	1 ppm	44A	34.96376315	-92.4285727	West side of 44 Starlite Rd	Exhaust fumes odor; Vac Trucks Present; Crude oil odor; Visible Oil; Area evacuated; Residence; Workers present; Slight Odor;	batch 211074 ATRID1852
04/06/2013	23:45	UltraRAE	Benzene	<	0.05 ppm	44A	34.96376315	-92.4285727	West side of 44 Starlite Rd	Exhaust fumes odor; Vac Trucks Present; Visible Oil; Area evacuated; Residence; Workers present; Slight Odor;	ATRID1852
04/06/2013	23:49	MultiRAE	VOC	0.7	0.1 ppm	44B	34.96382422	-92.4284833	West side of 44 Starlite Rd	Exhaust fumes odor; Vac Trucks Present; Crude oil odor; Area evacuated; Residence; No work activity; Workers not present; Moderate Odor;	ATRID1852
04/06/2013	23:51	MultiRAE	H2S	<	1 ppm	44B	34.96382422	-92.4284833	West side of 44 Starlite Rd	Exhaust fumes odor; Vac Trucks Present; Crude oil odor; Area evacuated; Residence; No work activity; Workers not present; Moderate Odor;	ATRID1852
04/06/2013	23:52	UltraRAE	Benzene	0.05	0.05 ppm	44B	34.96382422	-92.4284833	West side of 44 Starlite Rd	Vac Trucks Present; Crude oil odor; Area evacuated; Residence; No work activity; Workers not present; Moderate Odor;	ATRID1852
04/06/2013	23:55	Gastec 121L	Benzene	<	0.05 ppm	44B	34.96382422	-92.4284833	West side of 44 Starlite Rd	Exhaust fumes odor; Vac Trucks Present; Crude oil odor; Area evacuated; Residence; No work activity; Workers not present; Moderate Odor;	ATRID1852
04/06/2013	23:58	MultiRAE	VOC	<	0.1 ppm	50B	34.96407193	-92.4286207	East side of 50 Starlite Rd	Exhaust fumes odor; Vac Trucks Present; Crude oil odor; boom present; Area evacuated; Residence; No work activity; Workers not present; Moderate Odor;	ATRID1852
04/07/2013	00:00	MultiRAE	H2S	<	1 ppm	50B	34.96407193	-92.4286207	East side of 50 Starlite Rd	Exhaust fumes odor; Vac Trucks Present; boom present; Area evacuated; Residence; No work activity; Workers not present; Moderate Odor;	ATRID1852
04/07/2013	00:00	UltraRAE	Benzene	<	0.05 ppm	20B	34.96350363	-92.42699492	East side of 20 Starlite Rd	Exhaust fumes odor; Vac Trucks Present; Crude oil odor; boom present; Area evacuated; Residence; No work activity; Workers not present; Moderate Odor;	ATRID1852
04/07/2013	00:02	MultiRAE	VOC	<	0.1 ppm	50A	34.96396138	-92.4287148	East side of 50 Starlite Rd	Exhaust fumes odor; Vac Trucks Present; Crude oil odor; boom present; Area evacuated; Residence; No work activity; Workers not present; Moderate Odor;	ATRID1852
04/07/2013	00:02	MultiRAE	H2S	<	1 ppm	50A	34.96396138	-92.4287148	East side of 50 Starlite Rd	Exhaust fumes odor; Vac Trucks Present; Crude oil odor; boom present; Area evacuated; Residence; No work activity; Workers not present; Moderate Odor;	ATRID1852
04/07/2013	00:02	UltraRAE	Benzene	<	0.05 ppm	50A	34.96396138	-92.4287148	East side of 50 Starlite Rd	Exhaust fumes odor; Vac Trucks Present; Crude oil odor; boom present; Area evacuated; Residence; No work activity; Workers not present; Moderate Odor;	ATRID1852
04/07/2013	01:56	MultiRAE	VOC	<	0.1 ppm	3A	34.96296078	-92.42865382	West side of 3 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1852
04/07/2013	01:57	MultiRAE	H2S	<	1 ppm	3A	34.96296078	-92.42865382	West side of 3 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1852
04/07/2013	01:57	UltraRAE	Benzene	<	0.05 ppm	3A	34.96296078	-92.42865382	West side of 3 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1852
04/07/2013	01:58	MultiRAE	VOC	<	0.1 ppm	3B	34.96312837	-92.42864003	West side of 3 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1852
04/07/2013	01:59	MultiRAE	H2S	<	1 ppm	3B	34.96312837	-92.42864003	West side of 3 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1852
04/07/2013	01:59	UltraRAE	Benzene	<	0.05 ppm	3B	34.96312837	-92.42864003	West side of 3 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1852
04/07/2013	02:00	MultiRAE	VOC	<	0.1 ppm	3D	34.96309517	-92.42844217	East side of 3 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1852
04/07/2013	02:01	MultiRAE	H2S	<	1 ppm	3D	34.96309517	-92.42844217	East side of 3 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1852
04/07/2013	02:03	MultiRAE	VOC	<	0.1 ppm	3C	34.96293615	-92.42844266	East side of 3 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1852

04/07/2013	02:04	MultiRAE	H2S	<		1 ppm	3C	34.96293615	-92.42844266	East side of 3 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1852
04/07/2013	02:04	UltraRAE	Benzene	<		0.05 ppm	3C	34.96293615	-92.42844266	East side of 3 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	batch 303024 ATRID1852 decon set up in street
04/07/2013	02:02	UltraRAE	Benzene	<		0.05 ppm	3D	34.96309517	-92.42844217	East side of 3 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	batch 303024 ATRID1852
04/07/2013	02:05	MultiRAE	VOC	<		0.1 ppm	31A	34.9630789	-92.42817822	East side of 31 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	equipment traffic along street ATRID1852
04/07/2013	02:09	MultiRAE	H2S	<		1 ppm	31A	34.9630789	-92.42817822	East side of 31 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	equipment traffic along street ATRID1852
04/07/2013	02:10	UltraRAE	Benzene	<		0.05 ppm	31A	34.9630789	-92.42817822	East side of 31 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	batch 303024 equipment traffic along street ATRID1852
04/07/2013	02:11	MultiRAE	VOC	<		0.1 ppm	31B	34.96294902	-92.42818009	East side of 31 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1852
04/07/2013	02:11	MultiRAE	H2S	<		1 ppm	31B	34.96294902	-92.42818009	East side of 31 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1852
04/07/2013	02:12	UltraRAE	Benzene	<		0.05 ppm	31B	34.96294902	-92.42818009	East side of 31 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	batch 303024 ATRID1852
04/07/2013	02:13	MultiRAE	VOC	<		0.1 ppm	27B	34.96294106	-92.42794491	East side of 27 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1852
04/07/2013	02:14	MultiRAE	H2S	<		1 ppm	27B	34.96294106	-92.42794491	East side of 27 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1852
04/07/2013	02:14	UltraRAE	Benzene	<		0.05 ppm	27B	34.96294106	-92.42794491	East side of 27 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	batch 303024 ATRID1852
04/07/2013	02:15	MultiRAE	VOC	<		0.1 ppm	27A	34.96309181	-92.42794563	East side of 27 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	dumpster along the street ATRID1852
04/07/2013	02:16	MultiRAE	H2S	<		1 ppm	27A	34.96309181	-92.42794563	East side of 27 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	dumpster along the street ATRID1852
04/07/2013	02:17	UltraRAE	Benzene	<		0.05 ppm	27A	34.96309181	-92.42794563	East side of 27 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	dumpster along the street batch 303024 ATRID1852
04/07/2013	02:18	MultiRAE	VOC	<		0.1 ppm	23B	34.9629492	-92.42768345	East side of 23 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1852
04/07/2013	02:20	UltraRAE	Benzene	<		0.05 ppm	23B	34.9629492	-92.42768345	East side of 23 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	batch 303024 ATRID1852
04/07/2013	02:20	UltraRAE	Benzene	<		0.05 ppm	23B	34.9629492	-92.42768345	East side of 23 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	batch 303024 ATRID1852
04/07/2013	02:19	MultiRAE	H2S	<		1 ppm	23B	34.9629492	-92.42768345	East side of 23 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1852
04/07/2013	02:21	MultiRAE	VOC	<		0.1 ppm	23A	34.96307496	-92.42768047	East side of 23 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1852
04/07/2013	02:21	MultiRAE	VOC	<		0.1 ppm	23A	34.96307496	-92.42768047	East side of 23 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1852
04/07/2013	02:21	MultiRAE	H2S	<		1 ppm	23B	34.9629492	-92.42768345	East side of 23 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	equipment traffic along street ATRID1852
04/07/2013	02:21	MultiRAE	H2S	<		1 ppm	23B	34.9629492	-92.42768345	East side of 23 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	equipment traffic along street ATRID1852
04/07/2013	02:22	UltraRAE	Benzene	<		0.05 ppm	23A	34.96307496	-92.42768047	East side of 23 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	equipment traffic along street ATRID1852
04/07/2013	02:22	UltraRAE	Benzene	<		0.05 ppm	23A	34.96307496	-92.42768047	East side of 23 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	equipment traffic along street ATRID1852
04/07/2013	02:23	MultiRAE	VOC	<		0.1 ppm	19B	34.9629537	-92.42744235	East side of 19 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1852
04/07/2013	02:25	MultiRAE	H2S	<		1 ppm	19B	34.9629537	-92.42744235	East side of 19 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1852
04/07/2013	02:25	UltraRAE	Benzene	<		0.05 ppm	19B	34.9629537	-92.42744235	East side of 19 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	batch 303024 ATRID1852
04/07/2013	02:26	MultiRAE	VOC	<		0.1 ppm	19A	34.96307978	-92.42743124	East side of 19 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	dumpster along street ATRID1852
04/07/2013	02:27	MultiRAE	H2S	<		1 ppm	19A	34.96307978	-92.42743124	East side of 19 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	dumpster along street ATRID1852
04/07/2013	02:28	UltraRAE	Benzene	<		0.05 ppm	19A	34.96307978	-92.42743124	East side of 19 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	dumpster along street batch 303024 ATRID1852
04/07/2013	02:29	MultiRAE	VOC	<		0.1 ppm	15B	34.96297452	-92.42718477	East side of 15 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1852
04/07/2013	02:30	MultiRAE	H2S	<		1 ppm	15B	34.96297452	-92.42718477	East side of 15 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1852
04/07/2013	02:30	UltraRAE	Benzene	<		0.05 ppm	15B	34.96297452	-92.42718477	East side of 15 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	batch 303024 ATRID1852
04/07/2013	02:31	MultiRAE	VOC	<		0.1 ppm	15A	34.9630627	-92.42717703	East side of 15 Starlite Rd	No Visible Oil; Vac Trucks Present; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	vac truck across street slight oil odor ATRID1852
04/07/2013	02:32	MultiRAE	H2S	<		1 ppm	15A	34.9630627	-92.42717703	East side of 15 Starlite Rd	No Visible Oil; Vac Trucks Present; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	vac truck across street slight oil odor ATRID1852
04/07/2013	02:33	UltraRAE	Benzene	<		0.05 ppm	15A	34.9630627	-92.42717703	East side of 15 Starlite Rd	No Visible Oil; Vac Trucks Present; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	batch 303024 vac truck across street slight oil odor ATRID1852
04/07/2013	02:34	MultiRAE	VOC	<		0.1 ppm	11B	34.96297473	-92.42693187	East side of 11 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1852
04/07/2013	02:35	MultiRAE	H2S	<		1 ppm	11B	34.96297473	-92.42693187	East side of 11 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1852
04/07/2013	02:35	UltraRAE	Benzene	<		0.05 ppm	11B	34.96297473	-92.42693187	East side of 11 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	batch 303024 ATRID1852
04/07/2013	02:36	MultiRAE	VOC	<		0.1 ppm	11A	34.96307178	-92.42693149	East side of 11 Starlite Rd	No Visible Oil; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	dumpster across the street slight oil odor ATRID1852
04/07/2013	02:37	MultiRAE	H2S	<		1 ppm	11A	34.96307178	-92.42693149	East side of 11 Starlite Rd	No Visible Oil; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	slight oil odor dumpsters across the street ATRID1852
04/07/2013	02:38	UltraRAE	Benzene	<		0.05 ppm	11A	34.96307178	-92.42693149	East side of 11 Starlite Rd	No Visible Oil; Area evacuated; Residence; No work activity; Workers not present; Slight Odor;	slight oil odor dumpsters across the street batch 303024 ATRID1852

04/07/2013	02:40	MultiRAE	VOC	<	0.1 ppm	7A	34.96307965	-92.42666186	East side of 7 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1852
04/07/2013	02:40	MultiRAE	H2S	<	1 ppm	7A	34.96307965	-92.42666186	East side of 7 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1852
04/07/2013	02:41	UltraRAE	Benzene	<	0.05 ppm	7A	34.96307965	-92.42666186	East side of 7 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	batch 303024 ATRID1852
04/07/2013	02:41	MultiRAE	VOC	<	0.1 ppm	7B	34.96294961	-92.42666129	East side of 7 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1852
04/07/2013	02:42	MultiRAE	H2S	<	1 ppm	7B	34.96294961	-92.42666129	East side of 7 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	ATRID1852
04/07/2013	02:42	UltraRAE	Benzene	<	0.05 ppm	7B	34.96294961	-92.42666129	East side of 7 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	bstch 303024 ATRID1852
04/07/2013	02:42	UltraRAE	Benzene	<	0.05 ppm	7B	34.96294961	-92.42666129	East side of 7 Starlite Rd	No odor; No Visible Oil; Area evacuated; Residence; No work activity; Workers not present;	bstch 303024 ATRID1852